Market Release Note

MRN-TS0866-67-121818

Product number:	TS0867S
Product description:	Intelligent Four Door Controller Firmware
Product version:	R121818.32269
Affected parts:	TS0866, TS0866B, TS0867, TS0867B
Release date:	4 January 2019

This firmware addresses an issue in R082417 relating to relay boards on the Four Door Controller.

Resolved Issues

- Resolved issue where time zone 42 would not work correctly
- Resolved issue where users could be lost in certain conditions
- Resolved issue where there was an excessive delay in unlocking the door when interlocking was used. Delay has now been halved.
- Resolved issue where door timer wouldn't run after cancelling shunt timer, resulting in getting a forced door alarm incorrectly
- Resolved issue where relay expansion boards fitted to TS0866 and TS0867 do not function

Documentation and Downloads

Access to this firmware release is via Hills. Please contact your local Hills branch for access.

Alternatively, please speak to you Interlogix sales representative for more information on product pricing and availability.

Marketing Collateral	Intelligent Four-Door Controller datasheet
	Tecom Portfolio Compatibility Matrix

All downloads can be found at www.interlogix.com.au/downloads