

## Market Release Note

MRN-TS1016-V10-06.46381

---

Product number: TS1016, TS1016B

Product description: Challenger10

Product version: V10-06.46381

Release date: 1 November 2019

---

## Resolved Issues

- Resolved polling issues with TS1020 DGPs, where they required a reboot after a panel upgrade in order to restore polling. Polling is now resumed correctly.

## Documentation and Downloads

<b>Marketing Collateral</b>	<a href="#">Challenger10 datasheet</a>
	<a href="#">Tecom Compatibility Matrix</a>
<b>Technical Manuals</b>	<a href="#">Challenger Series Programming Manual</a> *
	<a href="#">Challenger Series Users Manual</a>
	<a href="#">Challenger Series Administrators Manual</a>
	<a href="#">Challenger Series Installation and Quick Programming Manual</a>
<b>Firmware Download Challenger10/SE</b>	<a href="#">Challenger10 firmware V10-06.46381</a>

\* Available via password protected access on the Interlogix Support Portal.

All downloads can be found at [www.interlogix.com.au/downloads](http://www.interlogix.com.au/downloads)

## Known issues

- Any Challenger10 or ChallengerSE panel upgrading from a version of firmware older than V10-06 will be classed as a new panel type when updated to this firmware. This means that the panel record will need to be converted to the new type in the software (Security Commander, Titan, Forcefield). Please refer to the manuals or call the technical support department if further information is required.
- Non-pollled peripherals are not backed up or restored when using the SD card.
- When using a TS1084 IUM, user names are not stored in the panel.
- When the option for 'Enable V8 Numbering' is toggled, input programming and numbering will not be altered. If this option is set incorrectly, inputs may not function as expected, and input names may appear to be incorrect.