

### **Market Release Note**

#### MRN-TS1016-V10-06-R8

Product number: TS1016, TS1016B

Product description: Challenger10

Product version: V10-06.19251

Affected parts: TS1016, TS1016B

Release date: 4 October 2018

### New features

 Improved security for comms paths, which can now be configured as either the existing 10-digit security password, or a username/password

# **Improvements**

 APN Username (for 3G Communications Module) has been extended to a maximum of 40 characters (Requires TS1053 firmware V01-01-19283)

## Resolved Issues

 Resolved issue where user PINs were sometimes not able to be reassigned to another user after being deleted



### **Documentation and Downloads**

Marketing Collateral	Challenger10 datasheet
	Tecom Compatibility Matrix
Technical Manuals	Challenger Series Programming Manual
	Challenger Series Users Manual
	Challenger Series Administrators Manual
	Challenger Series Installation and Quick Programming Manual
Firmware Download Challenger10	Firmware download - ZIP file
	Firmware download - SREC file

All downloads can be found at <a href="https://www.interlogix.com.au/downloads">www.interlogix.com.au/downloads</a>

### Known issues

- Any Challenger10 or ChallengerSE panel upgrading from a version of firmware older than V10-06 will be classed as a new panel type when updated to this firmware. This means that the panel record will need to be converted to the new type in the software (Security Commander, Titan, Forcefield). Please refer to the manuals or call the technical support department if further information is required.
- Non-polled peripherals are not backed up or restored when using the SD card.
- When using a TS1084 IUM, user names are not stored in the panel.
- When the option for 'Enable V8 Numbering' is toggled, input programming and numbering will not be altered. If this option is set incorrectly, inputs may not function as expected and input names may appear to be incorrect.